

## **HOW TO PRESS A SINGLE TILE**

1. MAKE TRANSFER LARGER THEN THE TILE BY AT LEAST 1". ADD A HAIRLINE OUTLINE THAT IS .025 LARGER THEN THE TILE. YOU WILL BE ABLE TO CENTER THE TILE EASIER WITH THE OUTLINE..
2. USING A HEAT RESISTANCE TAPE, TAPE TRANSFER FACE DOWN ON TILE. BE SURE TO TAPE TRANSFER ON ALL 4 SIDES.
3. WITH TILE FACING UP & TRANSFER TAPED FACE DOWN. LAY A BLANK SHEET OF PAPER ON TOP OF THAT. THEN LAY THERMAL TRANSFER GREEN SILICONE PAD ON TILE/TRANSFER.
4. PRESS AT 400 DEGREES FOR 5 MINUTES USING MEDIUM (35 LB) PRESSURE.
5. REMOVE TRANSFER IMMEDIATELY BEING VERY CAREFUL AS TILE IS EXTREMELY HOT.

**PRESSING TIMES MAY VERY SLIGHTLY. ADJUST ACCORDING TO YOU OWN PRESS. CHECK WITH EACH MANUFACTURE FOR PRESSING INSTRUCTIONS.**